

Description	Cat No.
TORCH PARTS & CONSUMABLES	
XT-300 TORCH HEAD	21-1001
Shield Cap, 30A, O2	21-1024
Shield Cap, 50A, O2	21-1025
Shield Cap, 70A, O2	21-1026
Shield Cap, 100A, O2	21-1027
Shield Cap, 150A, O2	21-1028
Shield Cap, 150A, O2	21-1275
Shield Gas Distributor, 30A, MS	21-1082
Shield Gas Distributor, 50-100A, MS	21-1272
Shield Gas Distributor, 150A, MS	21-1273
Tip, 30A, O2	21-1050
Tip, 50A, O2	21-1051
Tip, 70A, O2	21-1052
Tip, 100A, O2	21-1053
Tip, 150A, O2	21-1054
Electrode, 30A, O2	21-1068
Electrode, 50A, O2	21-1069
Electrode, 70A, O2	21-1070
Electrode, 100A, O2	21-1071
Electrode, 150A, O2	21-1072
Shield Cap, 50A, SS	21-1034
Shield Cap, 70A, SS	21-1035
Shield Cap, 100A, SS	21-1036
Shield Cap, 150A, SS	21-1037
Shield Gas Distributor, 50-100A, SS	21-1274
Shield Gas Distributor, 150A, SS	21-1278
Tip, 30A, SS	21-1059
Tip, 50A, SS	21-1060
Tip, 70A, SS	21-1061
Tip, 100A, SS	21-1062
Tip, 150A, SS	21-1062
Electrode, 30A, SS	21-1077
Electrode, 50A, SS	21-1078
Electrode, 70A, SS	21-1079
Electrode, 100A, SS	21-1080
Electrode, 150A, SS	21-1081
Gas Distributor, 30A, MS	21-1040
Gas Distributor, 50-150A	21-1041
Gas Distributor, 150A	21-1042
Gas Distributor, 30A, SS	21-1045
Shield Cup, 30-200A	21-1016
Consumables Cartridge, 30-100A	21-1020
Retaining Ring, Cartridge	21-1085
Coolant Tube	21-1086
Ohmic Sensor Assembly	21-1087
Tool, Cartridge	21-1088
O-RING, Electrode	9-9035
O-RING, Tip	9-9036
O-RING, Shield Cap	9-9037
O-RING, Shield Cap	9-9038
O-RING, Shield Cap	9-9039